INSURANCE INVOICE

000000039

BS-00213 - Mercedes-Benz GLS 580 2023

JD

Demo Collision Center

Demonstration workspace

Contact details hidden

Sample invoice - demonstration data

BILL TO

Insurance not assigned

Claim number: SAMPLE-213

Issue date: Nov 11, 2026

Due date: -

Status: Draft

Customer	Demo customer	Vehicle	QAB005 - Mercedes-Benz GLS GLS 580 2023	Accident date	Unknown

DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL
Occupant classification sensor **Procedure:** Assess the reported need, inspect related SRS/occupant-classification data, and determine whether initialization is applicable after the relevant repair. Do not treat this draft as calibration or completion instructions. **Affected systems:** Occupant detection **Component:** Occupant classification sensor **Location:** Passenger seat / occupant sensor	1	US$ 250.00	**US$ 250.00**
Seatbelt system **Procedure:** Review the requested concern, inspect accessible seatbelt webbing, buckles, anchors, pretensioner areas, and warning indications, then document visible findings and recommend further diagnosis if needed. Do not treat this scope as proof of system compliance or completed repair. **Affected systems:** Occupant protection **Component:** Seatbelt system **Location:** Seatbelt / pretensioner assemblies	1	US$ 100.00	**US$ 100.00**
Power liftgate / trunk **Procedure:** Confirm the trunk/liftgate concern and inspect related repair history or power interruptions. Determine whether vehicle-specific initialization may apply, then verify operation after any approved work; AutoOps360 AI does not confirm completion or provide OEM calibration instructions. **Affected systems:** Power closures **Component:** Power liftgate / trunk **Location:** Liftgate / trunk control	1	US$ 150.00	**US$ 150.00**

Subtotal	US$ 500.00
Taxes	US$ 0.00
Total	US$ 500.00
Paid by insurer	US$ 0.00
Balance due	US$ 500.00